	Type L#	#	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Err
-	BRS	8	27	1 and wood	USPAT; US-PGPUB; EPO; 2002/ JPO; DERWENT; IBM_TDB 08:41	2002/02/05 08:41			0
8	BRS	7	525	(steering adj wheel) and seam	USPAT; US-PGPUB; EPO; 2002/ JPO; DERWENT; IBM_TDB 08:54	2002/02/05 08:54			0
6	BRS	L15 8	∞	1 and (seam near5 rim)	USPAT; US-PGPUB; EPO; 2002/02/05 JPO; DERWENT; IBM_TDB 08:55	2002/02/05 08:55			0
4	BRS	122	2	1 and (seam with rim)	USPAT; US-PGPUB; EPO; 2002/ JPO; DERWENT; IBM_TDB 08:56	2002/02/05 08:56			0
ro	BRS	L 29	8	liquid adj pressure adj transfer adj printing	USPAT; US-PGPUB; EPO; 2002/ JPO; DERWENT; IBM_TDB 09:01	2002/02/05			0
9	BRS	L36	639	(steering adj wheel) and wedge	USPAT; US-PGPUB; EPO; 2002/ JPO; DERWENT; IBM_TDB 09:01	2002/02/05 :09:01			0
7	BRS	L 43	25	36 and 74/552.ccls.	USPAT; US-PGPUB; EPO; 2002/ JPO; DERWENT; IBM_TDB 09:04	2002/02/05 09:04			0
&	ERS	L50	80	(steering adj wheel) and (core with equal)	USPAT; US-PGPUB; EPO; 2002/ JPO; DERWENT; IBM_TDB 09:19	2002/02/05 09:19	,		0
6	BRS	L57 49	49	(steering adj wheel) and (rim with equal)	USPAT; US-PGPUB; EPO; 2002/ JPO; DERWENT; IBM_TDB 09:20	2002/02/05 09:20			0